ES9528/ES9528-XT
Firmware History (1800388)

Changes from v1.4b to v2.0
Removed Java requirement.

Changes from v1.4a to v1.4b
- NetVision protocol bug fixes

- Modify web interface with new RocketLinx web banner

- Fix web PVLAN configuration bug

- Add SNMP IPv6 support

- Add Ethernet/IP feature

Changes from v1.4 to v1.4a
- Update web interface with a signed JAR file so that Java 7/Update 51 permits the web interface to open.using the Java default security settings.

Changes in v1.4
- Fixed NetVision discovery bug

- Fixed IGMP IP subnet mask check

- Fixed web reboot bug

- EtherType help/storm control disabled

- VLAN max = 256

- Web save messaged changed

- Added DHCP server features
    - Option 82
    - DHCP Server assign IP address by Option82 content
    - DHCP Relay Agent can assign Circuit-ID and Remote-ID
    - DHCP Server assign IP address by Port
    - Port-based IP address assignment
- Added DHCP Relay Agent w/ Option 82 feature - Remote-ID can be specified by
    - MAC address
    - IP address
    - Arbitrary strings
- Added IPv6 address support
- Added enable/disable access to the switch via HTTP and Telnet
- Added Web save function
- Added new functions for NetVision
    - Password function
    - Gateway function
    - DHCP function
- Modified SSL Certificate Name