



ES7506

Firmware History (1800382)

Changes from v2.1b to v2.3

- Update web interface with a signed JAR file so that Java 7/Update 51 permits the web interface to open using the Java default security settings.
- Add DHCP Option 82 (DHCP relay) function
- Add IEEE 802.1AB LLDP function
- Change administrator password length from 8 to 32 characters. (Username length is the same. (20 characters))
- Update RocketLinx banner in web interface
- Change string "Factory default" to "Load default" in web page under Basic Settings
- Update pop up messages when changing IP addresses from DHCP to Static

Initial Release – v2.1b